



Rynna-line - Gutter Refurbishment Case Study

Lloyds Bank, Edinburgh

We recently collaborated with TEAM Ltd to address the persistent leaking gutter issues at Lloyds Bank in Edinburgh.

During a comprehensive site survey conducted in partnership with TEAM Ltd, it was discovered that the existing gutter system had been subjected to multiple applications of rubberised coating in an attempt to mitigate water ingress. While this method initially proved to be somewhat effective, it had ultimately proven to be inadequate in preventing further leaks.

In response to these findings, we proposed a comprehensive refurbishment solution utilizing our state-of-the-art Rynna-line gutter refurbishment system. This innovative solution offered a long-term, cost-effective remedy for the ongoing leaking gutter problems plaguing the building.



Specification

System:	Rynna-line
Total LM:	72lm
Client:	TEAM Ltd
Site Location:	Lloyds Bank, Edinburgh, Scotland